



IMMEDIATE STOP USE AND INSPECT NOTICE FOR PARK TOOL CRANK PULLERS

Park Tool has issued a Stop Use and Inspect Notice for their CCP-22, CCP-44 and CWP-7 crank pullers due to an out-of-spec nut that is shared between the three tools. This out-of-spec threading may cause damage to bicycle cranks during removal.

PART NUMBER AFFECTED: Park Tool CCP-22, CCP-44 and CWP-7 Crank Pullers.

MANUFACTURED DATE: Some, but not all, tools purchased between October 2021 and April 2022 may be affected.

INSPECTION OF TOOL: To see if your tool is affected, locate the nut on each of the tools per the images below and inspect the threading.



Bad threads will have a flat peak, and the improper thread peaks will extend almost halfway down the threading of the nut. The non-affected tools have sharper and consistent thread peaks throughout the length of the nut, as shown in the picture.



IF YOU HAVE CHECKED YOUR PULLER AND NEED A REPLACEMENT NUT,
PLEASE CONTACT US IMMEDIATELY.